4 Bar Skeleton Popup

First decapitate the weak head, remove foam from spine, and jam 3/4" dowel up spine to hold body and attach new head

Attach the new head after you

drill hole in it

Attach hinges on skelly

Waiting to spring across
the fence

Triggered

Triggered

Only took 25-30psi to lift a 10lb skelly

I used the 4 bar simulator to design the movement

Email csolsen@yahoo.com if you have questions